

Wood moisture meter
T G - 1 0 1
- Electric moisture meter -
Operating Instruction MANUALS

CAUTIONS:

- Before using the Meter, read this INSTRUCTION MANUAL thoroughly and use the Meter correctly.
- Keep this INSTRUCTION MANUAL with care and refer to it when necessary.
- In the event of any discrepancies, the original INSTRUCTION MANUAL in Japanese is to be of final authority.

1. Characteristics • Applications

- Capable of measuring moisture contents of timbers • wooden products by inserting (touching) a probe to measuring objects.
- MC (Moisture content) mode makes it possible to measure all kinds of objects.
Switching of the mode of a body is capable of comparing and classifying states of dryness • wetness of measuring objects with a displayed numerical value of 1 to 100(without unit) which leads to quick and easy checking

| | |
|------------------------------------|--|
| Woods (H, S) | Wooden products like Timbers, Constructing materials, Packing materials, Plywood, Compiled woods, Particle board, Furniture, Flouring woods, Textile materials, Household materials, etc. |
| Moisture content (MC-6) | Judging measurement results by comparing displayed numerical values of moisture content of textiles, foods, chemical synthesis, ceramics and so on, the methods of which were considered difficult to perform. |


2. Specifications

| | |
|---------------------------|--|
| Model | AQUA SEARCH SERIES TG-101 |
| Method | DC electric resistance type Dry weighted standard moisture% |
| Range | 6.0 to 50.0% , 1 to 100(MC mode) |
| Resolution | 0.1% , 1(MC mode) |
| Accuracy | ± 3% (read-out value) |
| Mode | Broad leaf tree (Hard), Conifer (Soft), Moisture content comparison |
| Average Value Display | Max. 20 points of average value data (Switch off to delete) |
| Display | LCD indication with HOLD function In addition to a measuring value, measuring mode, HOLD, TEMP, Upper limit value setting and Battery residue are displayed |
| Upper limit value setting | Setting of optional numerical value of upper limit 6.5 to 49.5% (0.5% step), MC: 2 to 99 (1 step) |
| Probe | Small stabbing (Inserting) type 2 needle electrode |
| Temperature compensating | Automatic temperature compensating function (ON-OFF function available) |
| Power | Alkali dry battery LR03 (1.5V) × 4, Non-stop running 100 hrs (approx.) Auto-power OFF |
| Operating temperature | 0 to 40 (Non-condensing) |
| Dimensions | 80(W) × 35(H) × 150(D) mm, 320g |
| Accessories | Carrying case, spare needles, Hexagon wrench (2 mm) |
| Option | SB metal net electrode, Conducting rubber electrode, Roller electrode, Moisture reading checker |

*** Specifications and appearances subject to change due to improvement without prior notice.**

3. Names

3-1 Main body



① Power SW (POWER)

Switch ON or OFF. Switch ON after a probe has been hooked up to a main body.

A display turns automatically to Error [E01] and Power-OFF because of Self Analysis Function when any abnormality is detected in the inner circuitry of a body.

② Hold•Average Key (HOLD/AVE)

It changes ON or OFF alternately whenever pushed.

A push of long periods (approx. 1 sec.) measures Average Statistical Mode (Max. measuring point 20).

An average value can automatically be displayed after 20 points have been measured.

Repress the key to stop the measurement for getting an average value at less than 20 points.

A push of long periods (approx. 2 sec.) releases the mode and turn to a normal measurement.

And POWER OFF also releases the mode.

③ Mode Change Key (G)

It turns to H (Broad leaf tree:HARD), S (Conifer:SOFT) or MC-6 (Moisture content) mode for each moisture measurement.

④ Numerical value setting key (▲ , ▼)

This is a key to set to an upper limit value.

The 「▲」, 「▼」 key moves up and down by a 0.5% notch (a 1 notch for MC mode) and keep the key pushed for a fast forward winding (rewinding).

The 「▼」 Key makes it possible to delete a point only of a latest measuring value at Average Statistical Mode in a measuring process.

Switch the Automatic temperature compensating function to ON or OFF. Refer for details to 「7. About temperature compensating」.

⑤ Lock key (LOCK)

A push of a Lock key locks all the keys except POWER SW which prevents erroneous operations. Switch OFF to release the lock.

⑥ Upper Limit Value Key (H)

Switch on Upper Limit Value Mode.

Set to an optional numerical value with a numerical value setting key .

⑦ LCD Display

Measuring Modes, measuring values, upper limit setting, temperature compensating, battery residue and so on are to be indicated on the LCD.

⑧ Probe connector receptacle

This is a connector to be hooked up to a probe.

⑨ Hand strap


To protect this instrument from dropping, make sure that the hand strap be hung through over an operator's wrist.

⑩ Battery Case (back Lower part of a main body)

Batteries are to be placed.

3-2 Probe

Small type 2 needles probe



⑪ Probe Connector

⑫ 2 needle electrode

⑬ Needle fixing block

⑭ Hexagon socket set screw for needle fixing

⑮ Handle

⑯ Probe Cord


4. How to use

4-1 Connection or disconnection of probe

(ensure that Power Source of a main body is OFF).


- Hook up the Probe connector to a main body to meet the Arrow Mark of the Probe Connector with the Mark of Probe Connector Receptacle and insert it carefully up to the end of a stroke.
- Switch Power OFF to disconnect Probe Connector from the receptacle.

* Unnatural force in inserting and pulling off may cause damages to connectors in a receptacle and a cord.



4-2 POWER ON•OFF


- Press Power SW to emit a “Peep” sound ,and “LLL” and Measuring Mode ”H” Broad Leaf Tree mark are displayed .
- Press again to switch OFF, emitting a “Peep” sound to turn off the display.
- Availability of Auto-Power-OFF preventing batteries from being consumed when Power is forgotten to switch off. An interval of 3 minutes without operation of measuring will automatically switch off.



* Press Power SW to ON or OFF at an interval of 3 to 5 seconds to prevent operating errors.

4-3 Changes of Measuring Mode


- When Power is ON, 「 H 」 Broad Leaf Tree Mode is displayed.
- For changes of Measuring Mode, press a Mode-Change 「 G 」 key to change the following turns by each press.




- Returning again to ON from OFF, the mode automatically returns to an initial measuring modes. Confirm a measuring mode when Power is ON.
- 「TEMP」 is not displayed with the MC mode of Moisture Content because there is no temperature compensating with the mode.

4-4 Changes of Hold Mode

A press of Hold • Average Key turns to the Hold Mode with a 「peep」 sound. Each press of the key changes the Hold Mode alternately to ON or OFF and 「Hold」 is displayed on LC Display when ON is in process. The displayed measuring value is on hold until a next measuring value has been input.





- * A press of long periods (approx. 1 sec.) turns to Average Value Mode (temporal memory). To release it, press again and hold the Hold • Average Key for long periods (approx. 2 sec.).




4-5 Setting of Upper Limit Values

- Press the Upper Limit Value Key 「H」 when Power ON is in process.
- A buzzer emits 「peep」 sounds and the 「H」, 「」 marks of an upper limit value indications and 「50.0%」 of the range of the upper limit are displayed.
- Press and hold a 「」 key until it has reached to a desired upper limit value. Keeping the 「」 key pressed changes to a fast winding of numerical values.
- Release your finger of the 「」 key when the values has reached to a desired value.
- When the value has reached too small beyond the desired one, press the 「」 Key to adjust the value .
- Set an upper limit value by pressing the 「H」 key again.
- A buzzer emits a “Peep” sound and the upper limit setting mark 「」 is indicated on the edge of the left side of LCD display .




ex) set upper limit value to 20%



- * An interval between setting values is a 0.5% notch.
- * “TEMP”, “HOLD” is not displayed during in process of setting.
- * Possible to activate the same operations even at the MC mode.


- At a real time measuring, it sounds a buzzer “ Peep, Peep, Peep “ when a measuring value exceeds a setting value, and the upper limit value and the measuring value alternately blinks on the display while being probed to contact. Releasing the probe turns to 「 LLL 」 on display.
- At a Hold Mode measuring, when it exceeds the setting value and even after releasing the probe off the object, the upper limit value and the measured value are alternately kept blinking.



- Press a 「 H 」 key again and repeat the same procedures as before to change upper limit values. Possible to operate the same procedures during measuring in process (Hold mode or Non-Hold mode).
- * When Upper Limit Value is unnecessary for an initial operation, press again the 「 H 」 key after pressing first the 「 H 」 key. In this case the Upper Limit Value is set at 50%, Maximum.
- * To delete an Upper Limit Value, set the Upper Limit Value at 50 % or switch Power to OFF. And the Upper Limit Value will also be deleted when Power switches OFF with Auto-Power-Off.

4-6 Changes of Key –Lock Mode


A press of a Lock Key locks all the keys except Power SW and prevents erroneous operations. Switch off Power to release.



5. Measurements

5-1 Real time measurement


1. Turn on Power SW and confirm an indication of LCD.



Display of a measuring mode 「H」Broad Leaf Tree and 「LLL」

- Turning on Power while inserting the probe to the object indicates 「LLL」 once on the display and then displays a measuring value in 2 to 3 seconds.
2. Select a mode suitable for the measuring object by pressing a Mode Change key「G」. (refer to 4-3 changes of measuring modes page at 5)
 3. Wait for reading the display until the display has become stable by inserting Electrode into the measuring object.

4. Press a Hold• Average key to display 「0.0 %」 with a sound of “Peep”. When probing an object, it emits “peep, peep” sounds and when releasing it, a “peep” sound again with a measured valued indicated on LCD.




- * **Do not probe other object until the above sounds of 3 times has finished otherwise that may cause measurement errors.**

An indicated value does not change when a measured value indicates not more than the measurement range.


When a measured value indicates not less than the measurement range,

「HHH」 blinks with sounds of “peep, peep, peep”.

Releasing a probe displays 「0.0%」.



5. Press a Hold • Average key again for releasing the Hold state.




Note) When stubbing a probe into a measuring object:

Keep Hold Mode released until stubbing has been completed. Make sure of changing to Hold Mode to read a measured value after finishing the stubbing.

(Stubbing during a Hold mode in process may cause measurement errors because it displays data while in process of stubbing.)


5-2 Measurement of Average Value Indication (Temporary Memory)

1. A long press (approx. 1 sec.) of a Hold • Average Key performs temporary Memory Measurement to display Average Value Indications.
(A max. measurement point capable for Temporary Memory is 20)




2. This Temporary Memory can be deleted when Power is OFF
(and Auto-Power OFF is as well)

3. Average Value Measurement is performed in a measurement of Hold Mode.
Measured data memory is capable of memorizing temporarily 「 AVE 1 」 , 「 AVE 2 」 , and 「 AVE 20 」 at the Maximum.



4. A press of the Hold • Average key during in process of the measurement turns to Average Value mode and on LCD 「 AVE__ 」 is indicated and shows the average value measured up to the points.
Then by operating numerical value setting keys 「 」 , 「 」 , measured values can be recalled and confirmed.




On the place of [AVE] on display, recalled measured numbers (1 to 20) are indicated and each measured value can also be confirmed respectively.
And then [HOLD] or [AVE] is not indicated.



- * During this mode, Auto Power OFF can not be operated.
- * An Average Value Mode can not return to a measuring operation.
When returning, refer again to 7. below and try to set again.


5. When reading erroneous data during a measurement of Average Value Indications, a long press and hold (approx. 1 sec.) of a Numerical Value Setting Key 「 」 is capable of deleting the only last data stored
(* Only possible to operate the latest measured data.)

6. When measured numbers has reached 20 items, it automatically turns to Average Value Indication mode in a second (the data at the 20th can not be deleted by operating any keys)
Release the mode to return to a measuring operation.



1 second after

7. A long press and hold (approx. 2 sec.) of the Hold • Average key make it possible to release the mode.



- Power SW key and Hold • Average key can only be used during a measurement in process of Average Value Indication.
- During a measurement of Average Value Indication, a setting function of Upper Limit Values turns ineffective. When actuating Average Value Indication measurement during a use of a setting function of Upper Limit Value, the setting function of an Upper Limit Value turn ineffective. But, even in this case Upper Limit Value is being in process of storing unless Power is switched OFF, and it returns to the Upper Value setting when a measurement of Average Value Indications has finished.

6. Measurement of MC(Moisture Content) mode


Select Moisture Content Mode by pressing a Mode Change key after turning Power to ON.

This MC mode is capable of using broad objects relating to Resistance.

Changes of electric resistance depending on dryness and moisture indicates numerical values


「1 to 100」 (No Unit) . Checking relatively comparative values makes it easy to classify and compare objects.

This MC measurement mode as well as when measuring Moisture can use all the functions although each of them does not display [%] .




7. About Temperature Compensating

- Automatic Temperature Compensating Function is set to ON at the initial setting of this meter and the LCD indicates [TEMP] .
(There is no Temperature Compensating with the MC mode measurement.)



- Auto Temperature Compensation function is performed at a basis of an indicated value of 20 C.
- Turn Auto Temperature Compensation function to OFF for measurements when measuring objects are heated up because of a baking (dry) heat treatment.
- Differences of temperatures between a main body and a probe cause measurement errors.
- Press 「 」 and 「 」 of Numerical Value setting keys at the same time to change Auto Temperature Compensation to ON or OFF.



And then that make it possible to understand the changes whether [TEMP] is indicated or not on the LCD , depending on the key operations.

- A setting of ON or OFF of Auto Temperature Compensating is kept alive even if the mode changes.

Refer to the table below for compensate the temperature and kind of wood of electric resistance type wood moisture meter.

| Moisture(%) Temperature(°C) | 4 to 11 | 12 to 20 | above or 21 |
|--------------------------------|---------|----------|-------------|
| below 0 | +2.0 | +2.5 | +3.0 |
| 0 to 1 | +2.0 | +2.5 | +3.0 |
| 2 to 3 | +2.0 | +2.0 | +3.0 |
| 4 to 5 | +1.5 | +2.0 | +2.5 |
| 6 to 7 | +1.5 | +1.5 | +2.0 |
| 8 to 9 | +1.0 | +1.5 | +2.0 |
| 10 to 11 | +1.0 | +1.0 | +1.5 |
| 12 to 13 | +1.0 | +1.0 | +1.0 |
| 14 to 15 | +0.5 | +0.5 | +1.0 |
| 16 to 17 | +0.5 | +0.5 | +0.5 |
| 18 to 19 | 0 | +0.5 | +0.5 |
| 20 to 21 | 0 | 0 | 0 |
| 22 to 23 | 0 | -0.5 | -0.5 |
| 24 to 25 | -0.5 | -0.5 | -0.5 |
| 26 to 27 | -0.5 | -0.5 | -1.0 |
| 28 to 29 | -1.0 | -1.0 | -1.0 |
| 30 to 31 | -1.0 | -1.0 | -1.5 |
| 32 to 33 | -1.0 | -1.5 | -2.0 |
| 34 to 35 | -1.5 | -1.5 | -2.0 |
| 36 to 37 | -1.5 | -2.0 | -2.5 |
| 38 to 39 | -2.0 | -2.0 | -3.0 |
| above or 40 | -2.0 | -2.5 | -3.0 |

| Moisture(%) Kind of wood | 4 to 7 | 8 to 11 | 12 to 20 | 21 to 30 |
|-----------------------------|--------|---------|----------|----------|
| Ash , Elm | -0.5 | -1.0 | -1.0 | -1.0 |
| Japanese oak , Linden | 0 | 0 | +0.5 | +0.5 |
| Beech | 0 | 0 | 0 | +0.5 |
| Cherry tree , Chestnut tree | 0 | 0 | +0.5 | +0.5 |
| Katsura wood , Birch | +0.5 | +0.5 | +1.0 | +1.0 |
| Oak , Zelkova | 0 | 0 | 0 | 0 |
| Apitong | -1.0 | -1.0 | -2.0 | -2.5 |
| Castor aralia , Lauan | +0.5 | +1.0 | +2.0 | +4.0 |
| Japan cedar | +0.5 | +0.5 | +1.0 | +2.0 |
| Japanese cypress , Pine | +0.5 | +1.0 | +2.0 | +3.0 |
| Fir | 0 | 0 | +1.0 | +2.0 |
| Magnolia obovata | +1.0 | +1.5 | +3.0 | +4.0 |

Extracted from the 「 Electric Moisture Meters 」 issued in 1960 by THE NIKKAN KOGYO SHINBUN, Ltd

8. Remarks on measurements

Measuring values may disperse according to measuring circumstances.

Electric Resistor Type Moisture meters use the applications of sensitively electric characteristics of measuring objects against the moisture contents and the corresponding relations never be a perfectly correlative one- to- one. In case of measuring wood barks, grains, faces, knots ,albeit the same material , or woods with changes in quality, salty, contamination, and furthermore with special processing, chemical treatments, it may be necessary to avert measuring such unfavorable objects, and compensate or average measured values. As for compensating, it is, in general, based on moisture measurement methods in accordance with a drying process.

(refer to previous page for compensate the kind of wood)

9. Dry batteries

9-1 Indication of Voltage-drop


Batteries run short when a battery mark indicating the state of charge of the batteries turns to 1 on the left lower side of LCD . By sliding open the lid of the battery case placed on the backside of a main body, replace all the old batteries with new ones (watch battery life). Alkali dry battery(LR03) × 4

In case batteries are kept used with a battery mark 1, the mark turns to a battery frame only (no charge of the batteries) and in Approx. 5 seconds Power will switch OFF, ceasing further uses.


Battery residue indication



well remained



less remained



least remained



Power will switch off in 5 seconds.
 Replace them with new ones.

9-2 Batteries while not in use.

- Batteries drain a minimum even while not in use.
- In case of keeping a meter unused for more than a month, remove the batteries from the case for storing.

10. Maintenance • Preservation

- * Clean and wipe off dirt with soft clothes. Pay attention to connector part, electrodes and grooves of electrodes of a probe and keep them clean and dry.
- * Prevent a meter from impulse, direct sunlight, and high humidity.
- * Choose a clean and dry place for preservation.

Remove batteries from the case for a long-term preservation.

11. Others


11-1 How to use moisture reading checker (option)

Touch the electrode to the checker illustrated below when Power is ON.

It is a good condition if indicated values are as per listed on the checker.

If indicated values deviate, contact a store or our sales office to get it corrected. (subject to pay)

- * Turn a Temperature Compensating Function to OFF to use the checker.
Refer to 「 7 About Temperature compensating 」 at page 10 in details.
- * Moisture Reading Checker has 2 different checking points in a front side and a back side.
Use the checker with confirmation of the object to be checked and a measuring mode without fail.




11-2 Needle electrode cover (Attaching and detaching of Needle electrode cover)

As illustrated below, insert the needle electrode cover to the electrode by pinching the both side of the cover with fingers. If it is tight, pick the cover by pushing it against the needle electrode.

Note: Please align the cover in line with the electrodes to push together for the insertion.

For detaching just remove the cover from the electrode by pinching it with fingers.

Unnecessary, unnatural force may cause damages. Attach or detach the cover with full care.




11-3 Replacement of needle electrodes

The needle electrode can be replaced loosing a Hexagon socket set screw for needle fixing with a furnished accessory Hexagon wrench.

Make sure that the hexagon socket set screw is set and screwed to strike a notch face of the needle electrode, otherwise it may cause the electrode to loose and drop off the body.

Hexagon socket set screw for needle fixing



Storage:

This moisture meter incorporates a Liquid Crystal Display (LCD).

If the display is heated above 50 (120°F) it may be damaged.

This can happen if the moisture meter is left in a car parked in strong sunlight.